

## POLINOMONO

Farblos	Add 0.75-3.50			Cil. < 6.00	Prisma < 3.00
	1.50 CR-39	1.53 Trivex	1.60 High index	1.60 Tribrid	1.67 High index
Ø 40/45	-12.00/+10.00	-12.00/+7.00	-13.00/+10.00	-13.00/+10.00	-15.00/+13.00
Ø 45/50	-12.00/+10.00	-12.00/+7.00	-13.00/+10.00	-13.00/+10.00	-13.00/+12.00
Ø 50/55	-11.00/+10.00	-11.00/+7.00	-13.00/+10.00	-13.00/+10.00	-13.00/+9.00
Ø 55/60	-11.00/+10.00	-11.00/+7.00	-12.00/+10.00	-12.00/+10.00	-12.00/+9.00
Ø 60/65	-11.00/+10.00	-10.00/+7.00	-11.00/+10.00	-11.00/+10.00	-11.00/+7.00

## POLINOMULTI

Farblos	Add 0.75-3.50			Cil. < 6.00	Prisma < 3.00
	1.50 CR-39	1.53 Trivex	1.60 High index	1.60 Tribrid	1.67 High index
Ø 40/45	-12.00 / +10.00	-12.00 / +7.00	-13.00 / +10.00	-13.00 / +10.00	-15.00/+13.00
Ø 45/50	-12.00 / +10.00	-12.00 / +7.00	-13.00 / +10.00	-13.00 / +10.00	-13.00/+12.00
Ø 50/55	-11.00 / +10.00	-11.00 / +7.00	-13.00 / +10.00	-13.00 / +10.00	-13.00/+9.00
Ø 55/60	-11.00 / +10.00	-11.00 / +7.00	-12.00 / +10.00	-12.00 / +10.00	-12.00/+9.00
Ø 60/65	-11.00 / +10.00	-10.00 / +7.00	-11.00 / +10.00	-11.00 / +10.00	-11.00/+7.00

## POLINOMYO

Farblos	Add 0.75-3.50			Cil. < 6.00	Prisma < 3.00
	1.50 CR-39	1.53 Trivex	1.60 High index	1.60 Tribrid	1.67 High index
Ø 50/55	-11.00/-0.25	-11.00/-0.25	-13.00/-0.25	-12.00/-0.25	-15.00/-0.25
Ø 55/60	-11.00/-0.25	-11.00/-0.25	-13.00/-0.25	-12.00/-0.25	-15.00/-0.25
Ø 60/65	-11.00/-0.25	-10.00/-0.25	-12.00/-0.25	-11.00/-0.25	-14.00/-0.25
Ø 65/70	-10.00/-0.25	-8.00/-0.25	-11.00/-0.25	-10.00/-0.25	-13.00/-0.25
Ø 70/75	-8.00/-0.25	-7.00/-0.25	-10.00/-0.25	-9.00/-0.25	-12.00/-0.25

 POLINOMONO

 POLINOMULTI

 POLINOMYO